


INSTRUCTIONS FOR USING YOUR G-3PS



1.

Unlock pusher assembly from the rear of the tool by pushing the unit in, then up and out.



2.

Remove the pusher assembly from the tool



3.

Load one strip of staples (*max 7/16"*) into the rear of the tool.



4.

Replace the pusher assembly and lock.

